



ROWELL MARINE

BROKERAGE

MARINA

SERVICES

RETAIL



52.0' Buizen Pocket Super Yacht

- American oak interior
- Teak Decks
- Hydraulic Opening Transom Garage
- Three Sleeping Cabins with Ensuites

- Raymarine Package Including Radar
- Inboom Hydraulic Main
- Hydraulic Furling Headsail
- Contemporary Interior

Construction:
Engine Type:
Accommodation:
Year:
Price:

GRP
Yanmar Turbo Diesel
2012
\$1,050,000









INVENTORY of Vessel: 52.0' Buizen Pocket Super Yacht

General

Boat Brand:	Buizen	Designer	Peter Lowe Design Team & Anthony Starr
Year Built:	2012	Draft	2.2m
Last Antifouled:	April 2016	Hull Material	GRP
Deck Material:	GRP	Cockpit Location	Stern
Steering System:	Hydraulic	Keel Material	Lead
Boat Type:	Mast Head Deck Saloon Sloop	Builder	Mastercraft Marine
Length Loa:	52'	Beam	4.76m
Displacement:	20,800Kg	Hull Finish	Awl Grip 2000 Epoxy Paint System, Silver
Steered By:	Twin Carbon Wheels	Keel Type	Moderate Fin 6.0 Tonne Lead Bulb
Bottom Condition:	Excellent		

Rigging

Rig Type:	Mast Head Sloop	Mast Material	Alloy
Standing Rigging:	Dyform S/S	Running Rigging	Braid, Concealed below decks
Furling:	Leisure Furl in Boom Main Sail	Spreaders	Three
Mast Finish:	Black Polurethane Paint	Age	2012
Backstay:	Twin with Hydraulic	Furler Brandtype	Harken Hydraulic

Engine Details

Brand:	Yanmar Turbo Diesel	Model	4LHA HTP
Cooling:	Fresh Water Cooled	Drive Type	Shaft
Cruise Speed:	7Knts	Fuel Type	Diesel
Material:	Poly	Bow Thruster	Yes
Cylinders:	4	Hp	160Hp
Engine Hrs:	155	Propeller	Folding
Max Speed:	9.5 Knts approx	Fuel Tank Size	1,200Ltrs
Last Serviced:	2015		

Sails

Main:	Hood Radial Cut Dacron (74.5scm)	Genoa	Hood Radial Cut Dacron (53.6scm)
--------------	----------------------------------	--------------	----------------------------------

Winches

Primary:	2 Harken Hydraulic /Electric ST 2 On Mast Speed		2 Harken ST,
Secondary:	Harken Hydraulic/Electric 2 Speed	Other	Harken Electric Headsail Furler

Anchoring

Primary:	Plough	Anchor Winch	Muir with Bow & Helm Controls
Chain Warp:	TBA	Other	Muir Anchor Monitor

Accommodation

Dining Table Capacity:	Six	Double Bunks	Master Forepeak Queen + Aft Double
Convertible Bunks:	Settee	Water Heating	Yes
Holding Tank:	Yes	Cabins	Three Sleeping Cabins
Single Bunks:	Aft Two Singles	Shower	Yes + Two Transom
Toilet:	Tecma Frash Water Flush X Two		

Galley

Water Tank Size:	793 Ltrs	Water Tank Material	Poly
Sinks Material:	S/S	Stove	LG Solar Dome with two glass hobs
Refrigeration:	Custm Full Height S/S 240V/12V Eutectic + Freezer	Crockery/cutlery	Yes

Sinks:	Franki	Sink Taps	Brodware Tap sets
Microwave:	Yes	Desalinator	Sea Recovery 142Ltrs Per Hour
Other:	Fisher & Paykel Dishwasher, Miele Washer/Dryer		

Electrical Equipment

Batteries:	Dedicated Batteries for all Systems, 12V & 24V	Generator	9.5Kva, Onan/Mase
Inverter:	Yes	Shore Power	Yes
Charging:	Allt/Shore Power/Generator	Solar Panels	No
Power Monitor:	BEP, Czone Electronic System Control	Navigation Lights	LED

Electronics & Instrumentation

Ele Radios:	Icom ICM505 Marine VHF	Speed Log	Raymarine C120 & C90 at Helm
Ele Wind:	Raymarine ST70 Mult Function	Ele Gps	Raymarine C120 + C90 in Cockpit
Ele Radar:	Raymarine Digital C120 & C90	Ele Television	Two Panel 32
Ele Horn:	Yes	Other Electronics	Aqualuma Under Water Lights, Raymarine AIS to C120 & C90
Ele Compass:	Plastimo X 3	Depth Sounder	Raymarine
Auto Pilot:	Raymarine SPX Control Head with Gyro X 2	Ele Plotter	Raymarine X 2 C120 Internal Helm + C90 Cockpit
Sound System:	Bose V35 Surround Sound +add amp for Cockpit	Ele Video	X 2 Blue Ray Players
Ele Barometer:	Yes		

Safety Equipment

Life Jackets:	Yes	Life Rafts	TBA
Epirb:	406	Bilge Pumps	Auto & Manual
Fire Extinguishers:	Yes		

Docking Equipment

Boat Hooks:	Yes	Fenders	Yes
Deckwash Pump:	Fresh Water Deck Wash	Cockpit Table	Yes
Docking Lines:	Yes	Hoses	Yes
Boarding Ladder:	Yes	Other	Aqualuma Under Water Lights X 4

Tender Equipment

Sun Awning:	Inserts, Between Dodger & Bimini	Emergency Tiller	Yes
Bimini:	Yes	Boom Tent	No
Lazy Jacks:	In Boom, Leisure Furl System		

Vessel details are supplied by the vendor. Whilst all care is taken in presenting the information accurately, the Broker accepts no responsibility for the information supplied. No warranty is expressed or implied. The Broker acts as the vendor's agent only.